



10/628,594.

cejl

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant: Robert C. Sundahl et al.

Examiner: Nguyen, Donghai

Patent No.: 7,191,515

Group Art Unit: 3729

Issue Date: March 20, 2007

Docket No: 884.264US2

Title: METHOD FOR MANUFACTURING AN INTERCONNECTED CIRCUIT BOARD ASSEMBLY


Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450
ATTN: CERTIFICATE OF CORRECTION BRANCH

We are transmitting herewith the attached:

- ☒ Request for Certificate of Correction.
- ☒ Certificate of Correction Form - PTO-1050 (in duplicate)
- ☒ A return postcard.


Please charge any additional fees or credit overpayment to Deposit Account No. 19-0743.

SCHWEGMAN, LUNDBERG, WOESSNER & KLUTH, P.A.
Customer No: 21186

By: 
Name: Viet V. Tong
Reg. No. 45,416
VVT:CMG:sj

CERTIFICATE UNDER 37 CFR 1.8: The undersigned hereby certifies that this correspondence is being deposited with the United States Postal Service with sufficient postage as first class mail, in an envelope addressed to: Commissioner of Patents and Trademarks, P.O. Box 1450, Alexandria VA 22313-1450, on this 17 day of April 2007.

Chris Hammond
Name


Signature

Certificate
APR 23 2007
of Correction

APR 23 2007



Patent 7,191,515

PATENT

IN UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 7,191,515 Docket No: 884.264US2
Issue Date: March 20, 2007 Patentee: Robert C. Sundahl et al.
Customer No.: 21186 Confirmation No.: 4636
Title METHOD FOR MANUFACTURING AN INTERCONNECTED CIRCUIT BOARD
ASSEMBLY

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450
ATTN: CERTIFICATE OF CORRECTION BRANCH

It is requested that a Certificate of Correction be issued correcting printing errors appearing in the above-identified United States patent. Two copies of the text of the Certificate in the suggested form are enclosed.

Issuance of the Certificate of Correction would neither expand nor contract the scope of the claims as properly allowed, and re-examination is not required.

As the error is that of the Patent Office, it is believed that no fee is due.

The Examiner is authorized to charge any additional fees or credit overpayment to Deposit Account No.19-0743.

Respectfully Submitted

ROBERT C. SUNDAHL ET AL.

By their Representatives,

SCHWEGMAN, LUNDBERG, WOESSNER & KLUTH, P.A.
P.O. Box 2938
Minneapolis, MN 55402
(612) 373-6900

Date : 4-16-07

By: [Signature]

Viet V. Tong
Reg. No: 45,416
VVT:sj

CERTIFICATE UNDER 37 CFR § 1.8: The undersigned hereby certifies that this correspondence is being deposited with the United States Postal Service with sufficient postage as first class mail, in an envelope addressed to: Commissioner for Patents, P.O. Box 1450 Alexandria, VA 22313-1450, on this 17 day of April 2007.

Chris Hammond
Name

Chris Hammond
Signature

APR 23 2007

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,191,515

Page (1) of 1

DATED : March 20, 2007

INVENTOR(S) : Sundahl et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 12, line 28, in Claim 18, after "pad." delete "attaching the first circuit board to the second circuit board."

MAILING ADDRESS OF SENDER:

SCHWEGMAN, LUNDBERG, WOESSNER, & KLUTH, P.A.
P.O. BOX 2938
Minneapolis, MN 55402

Atty Docket No: 884.264US2

PATENT NO. 7,191,515

No. of additional copies

➡

MAR 23 2007

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,191,515

Page (1) of 1

DATED : March 20, 2007

INVENTOR(S) : Sundahl et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 12, line 28, in Claim 18, after "pad." delete "attaching the first circuit board to the second circuit board."

MAILING ADDRESS OF SENDER:

SCHWEGMAN, LUNDBERG, WOESSNER, & KLUTH, P.A.
P.O. BOX 2938
Minneapolis, MN 55402

Atty Docket No: 884.264US2

PATENT NO. 7,191,515

No. of additional copies

APR 23 2007



APR 23 2007